



Technical Service Bulletin

No.LTB00067

21 June 2007

Subject/Concern: Audible 'Chirp' on Cold Start

Models:		
Discovery 3 / LR3	Gasoline V8 Only	Gasoline V8 Only VIN-range: 5A300394 Onwards
Range Rover (LM)	Gasoline V8 Only	Gasoline V8 Only VIN-range: 6A198058-7A257088
Range Rover Sport (LS)	Gasoline V8 Only	Gasoline V8 Only VIN-range: 5A900505 Onwards

Markets: All **Section:** 303-05

Summary:

Audible 'chirp' on cold start in a rhythmic pattern emanating from the front end accessory drive (FEAD) belt.

Cause: FEAD drive belt travelling/wandering on the idler pulley.

Action: Should a customer express concern, install a new modified idler pulley and FEAD belt.