No.LTB00247 17 November 2009

Subject/Concern: 08/09MY Accessory Rubber Mat Fitment

Models:

Range Rover Sport (LS) VIN-range: AA215623 Onwards

Markets: All RHD Markets

**Section:** 501-00

## Summary:

**This bulletin is for information only.** These rubber mats must only be fitted in 08/09 MY Right-Hand Drive vehicles. Under no circumstances should RHD 08/09 MY rubber mats be fitted to RHD 10MY vehicles.

Cause: There is a risk of insufficient clearance between the 08/09 MY RHD rubber mat and accelerator pedal of 10 MY on RHD vehicles which may cause the accelerator pedal to stick in the downward position. Fit only RHD 10MY front mats (Service Part number for Front RHD Front Pair Rubber Mat - VPLSS0019) to 10MY Range Rover Sport. These mats were introduced on 10/04/09. The change to the rubber mat was to remove the Castellation feature in the area of the Accelerator Pedal. The condition of throttle pedal interference with mat affects Accessory mats produced after September 2007 and prior to

10 April 2009 when installed on 10MY Range Rover Sport RHD only.

Action: For information see the Service Instruction below.

**NOTE:** For information only.

Parts Required:		
Description	Part Number	Quantity
10MY Floor Mats Front Pair	VPL SS019	1

## Service Instruction

1. Incorrect floor mats shown.



Correct floor mats shown.



©2009 LandRover